enforcement DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES 45th 7/01/17/70th 7/26/17 PKINTISU: UW HAGIT FORM APPROVED STATEMENT OF DEPICIENCIES OMB NO. 0938-0391 (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF COPRECTION (X2) MULTIPLE CONSTRUCTION IDENTIFICATION NUMBER: (X3) DATE SURVEY A. BUILDING Of - WAIN BUILDING OF COMPLETED 445483 B. WING NAME OF PROVIDER OR SUPPLIER 05/09/2017 STREET ANDRESS, CITY, STATE, ZIP CODE CORNERSTONE VILLAGE 2012 SHERWOOD DRIVE JOHNSON CITY, TN 37601 -SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL (X4) ID PREFIX PROVIDER'S PLAN OF CORRECTION Ç(0) COMPLIÇIYON PATI: REGULATORY OR LSC IDENTIFYING INFORMATION) TAO PRECIX FACH CORRECTIVE ACTION SHOULD BE CROSS REPERENCED TO THE APPROPRIATE TAG DEFICIENCY 1. The items that were noted during NFPA 101 Sprinkler Systom - Maintenance and K 353 survey as being stored within 1,8" of a K 353 6/15/17 SS≃Ľ Testing Sprinkler Head in the 3) pantry off of Sprinkter System - Malntenance and Testing dietary, 2) storage room on upper level Automatic sprinkler and standpipe systems are and 3) lower common area closet were Inspected, tested, and maintained in accordance removed on 5/9/17 with NFPA 25, Standard for the Inspection, All other storage areas in the facility Testing, and Maintaining of Water-based Fire were reviewed on 5/10/17 to ensure that Protection Systems. Records of system design, no items were found to be stored with maintenance, inspection and testing are maintained in a secure location and readily 18" of a Sprinkler Head and none were avallable. found to be out of compliance. a) Date sprinkler system last checked A systematic approach to ensure b) Who provided system test compliance with this standard will be to remove top shelves in storage areas and c) Water system supply source markwith red tape to ensure that there is 18" between the Item stored on the top Provide in REMARKS information on coverage for shelful a storage shelf and a Sprinkler any non-required or partial automatic sprinkler Head, height is clearly marked. The systom, 9.7.5, 9.7.7, 9.7.8, and NFPA 25 following staff will be educated on the This STANDARD is not mot as evidenced by: requirement that no storage item is to be Based on observation and interview, the facility placed within 18" of a Sprinkler Head: falled to maintain the automatic sprinkler system. This deficiency affected 3 of 11 smoke Maintenance Supervisory Staff, Dietary compartments. Supervisor Staff, Respiratory Managers, Therapy Managor, Director of Nursing, The findings include: Assistant Director of Nursing and Central Supply. An audit will be maintained to Observation and interview with the maintenance director on 6/9/17 between 9:62 AM and 11:30 ensure compliance with the standard. AW revealed storage within 18 inches of The Quality Assurance Staff will sprinklers in the following locations; maintain an audit on a monthly basis to ensure that no item in storage is placed in the pantry off of dietary. within 18" of a Sprinkler Head. The Storage room on upper level. Lower common area closet, results of the audit will be presented at NFPA 101, 19.3.5.1, NFPA 13, 8.5.6:1 the monthly Quality Assurance and Safety Committee moetings. LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE TITLE (X0) DATE AUN-NUS Any deficiency statement ending with an asteriek (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other ealleguards provide sufficient protection to the patients, (See Instructions.) Except for nursing homes, the findings dated above are discloseble 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the show findings and plans of correction are discloseble 14 days following the date those documents are made available to the facility. If deficiencies are olded, an approved plan of correction is requisite to continued

FORM CMS-(667(62-69) Praylous Versions Obpoloto

Evont ID: LW9W21

Facility (D: THOOS:

If continuation sheet Page 1 of 5

LM9WII

SCOPME

FORM CM8-2667 (02-99) Previous Versions Obsolete

Event ID: LIV9W21

Facility ID: TN9002

if continuation sheet Page 2 of 5

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		E & MEDICAID SERVICES (X1) PROVIDER/SUPPLIER/CLIA	CVO set umor or			FORM APPRO OMB NO. 0938- (XB) DATE SURVE COMPLETED	
		IDENTIFICATION NUMBER	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01				
NAME	E OF PROVIDER OR SUPPLIES	445483	_ B. Wing		•	-	
				~	TREET ANDRESS, CITY, STATE, ZIP CODE	· ·05	/09/20
COR	rnerstone Village		Ϊ	26	012 SHERWOOD DRIVE		
(X4)	D SUMMARY ST	ATEMENT OF DEFICIENCIES		J	Ohnson City, TN 97601	1	
TAG	G REGULATORY OR	A CAMENT OF DEFICIENCIES Y MUBT BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	,	PROVIDER'S PLAN OF CORRECTI (FACH CORRECTIVE AUTION SHOUL CRISS-REFERENCED TO THE APPRO DEFICIENCY)	16.00	(X) COMPT.
K7	711 Continued From pa	eria 2	1	T	1 The District Vitables as of the		<u> </u>
	80 emerganov		K7	11	1. The Dietary Kitchen staff that w	rere	-1
	Elimplovees are ner	iodically instructed and kept			working during survey and did no correct procedure for the kitchen	t use the	6/
		7711TIQC 11DYAF #K = #T *		1	suppression system during a fire d	nood tan	
	THE THE PROPERTY OF THE	(BOCO) COMMANDA INTERNA	[-	5/9/17 were immediately in-service	ILIN OU	
		outity. The plan eddresses the ulred of stell per 18/19.7.2.1.2	ĺ		the correct procedure on 5/9/17.	ced as to	
	Larra Gradings (0) Will	IN MICH TITO COTTON, WILL			2. All other Dietary Litelans start		
	LAACOMANIBORIS ONC. 18	MU 7 4			 2. All other Distary kitchen staff w serviced on the correct procedure 	ere In-	
	18.7.2.3 through 18	.7.1.3, 18.7.2.1.2, 18.7.2.2,			kitchen suppression system during	Tor the	
	19.7.22, 19.723	irougn 19.7.1.3, 19.7.2.1.2,		1.	kitchen fire drill on 5/10-12/17.	¦a .	
	This STANDARD is	not met as evidenced by:].	3. A systematic approach to ensure		,
		OD 900 mitations U c. m			compliance with this standard will	i hata	
***	1	IPTSITI CITTE IN ANA BALLETT IN I			educate the Dietary Kitchen Staff o	ne to	
	the kitchen hood sur components. This d	eficiency affected all smoke			correct procedure for the kitchen h	n uie	
	compariments.	and alleged all stucke			suppression system during a fire dr	1800	
	The finding to the	• .			during their new hire orientation.	A Rira	
•	The finding includes:			l	Drill audit of the kitchen staff for th	afr.	
	Observation and inte	rview with 2 of 2 dietary staff			appropriate response during a fire v	will he	
	t mannacia revesien w	IBN Mara tiat familian			maintained to ensure compliance w	ith the	
	I - " TOOL BUILDING	Cinn custom and			standard.		
1	19.3.2.5.3, NFPA 96,	Ven a scenario. NFPA 101,]	4. The Quality Assurance Staff will		
	1			Ì	maintain an audit on a monthly bas!	s to	
- 1	I no maintenance dire	ector was present when the			ensure all Dietary Kitchen Staff are		
İ	ACMOINTING MAS MENUL	ed and was acknowledged uring the exit conference on			responding appropriately by using th	1e	
			Į		kitchen hood suppression system du	ring a	
< 920 88=E	NFPA 101 Electrical E and Extens	quipment - Power Cords	K 920		. con	t.	
- 1	Electrical Equipment - Extension Cords	ı					
	Power strips in a patier used for components o	of movahle "	·				
	patient-care-related ele	etrical equipment					
70 EO GOW	/(02-99) Previoue Versions Obso]				

CENTERS FOR MEDICARI STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CUA IDENTIFICATION NUMBER:		TIPLE CONSTRUCTION ING 01 - MAN BUILDING 01	FORM APPRO OMB NO. 0938-0 (X3) DATE SURVEY	
		445483	B. WING		CON	PLETED
NAME OF	PROVIDER OR SUPPLIER		T To saling		05/	09/20 1 7 -
CORNE	RSTONE VILLAGE		.	STREET ANDRESS, CITY, STATE, ZIP CODE 2012 SHERWOOD DRIVE JOHNSON CITY, TN 37601		
PREFIX TAG		EMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL C IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORPECTIO	יחכי	COMPLETIO DATE
f ()	copy of the plan is re operator or with secularity basic response required and provides for all ocomponents per 18/118,7.1.1 through 18,7.1.1 through 18,7.2.2, 19,7.2.3 This STANDARD is a Based on observation is led to ensure all die he kitchen hood supproments. This decompartments.	dically instructed and kept uitles under the plan, and a adily available with telephone uity. The plan addresses the red of staff per 18/19.7.2.1.2 if the fire safety plan 9.2.2. 7.1.3, 18.7.2.1.2, 18.7.2.2, pugh 19.7.1.3, 19.7.2.1.2, not met as evidenced by: n and interview, the facility if any confirmance of the property of the plan interview, the facility interview that the plan is the plan interview.	K7		COINT, audit Jality	
o m ki	chen hood sunness	AD A Scenario - NEDA 404 - L				,
by 6/9 20 NF	niciency was identine ' the administrator du 9/17.	tor was present when the d and was acknowledged ring the exit conference on ulpment - Power Corde	K 920	2. The OL unapproved Power Strips the	it (5/15/17
Po	octrical Equipment - F fension Cords wer strips in a patien ed for components of tient-care-related elec	t care vicinity are only	j	werenoted in rooms 502, 507, 509 and 609 during survey in the resident's room that had not-medical equipment plugge into them were removed immediately fromservice on 5/9/17	ms	

FORM CNAS-2567 (02-99) Pravious Vereione Obsolete

Event ID: LW9W21

Facility ID; TYSO2

If continuetion sheet Page 3 of 5

cont.



		E & MEDICAID SERVICES (X1) PROVIDER/SUPPLIER/CLIA	Leverse		OMB NO	IAPPROVI . 0938-03	
AND PLAN OF CORRECTION		IDENTIFICATION NUMBER:	V DRING 61 - WAW BRITDING 01		(XX) DAT	COMPLETED (X3) DATE SHRVEY	
NAME OF		446483	B. WING_		ŀ		
	PROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CODE	05	09/2017	
CORNE	RSTONE VILLAGE			2012 SHERWOOD DRIVE			
(X4) ID	SUMMARYST	TEMENT OF DEFICIENCIES		JOHNSON CITY, TN 37601			
PRÉFIX 'IAG	I CAOR DEFICIENCE	Y MUST BE PRECEDED BY FULL SCIDENTIPYING INFORMATION)	PREFIX 174G	PROVIDER'S PLAN CX-CORRECT EACH CORRECTIVE ACTION SHOU CROSS-REFERENCED TO THE APPRO DEFICIENCY)	าก ๑๓	DATE COMPLETA (XO)	
() () ()	10.2.3,6. Power string not be used for electronics), except rooms that do not used for persons that do not used for more than the PCREE meet UL 13 strips for non-PCRE (outside of vicinity) rocare rooms, power a standards. All power than the precautions. Extens precautions. Extens with the for fixed we extension cords used mmediately upon control it was installed to 10.2,4. (NFPA 90), NFPA 70), 590.3(D) This STANDARD is Based on observational of the onsure approximation and the string process of the process of t	es that have been assembled not and meet the conditions of ips in the patient care vicinity non-PCREE (e.g., personal in long-term care resident se PCREE. Power strips for 63A or UL 60601-1. Power E in the patient care rooms neet UL 1363. In non-patient strips meet other UL retrips are used with general ion cords are not used as a wing of a structure. I demporarily are removed emploition of the purpose for land meets the conditions of 10.2.4 (NFPA 99), 400-8 (NFPA 70), TIA 12-5 not met as evidenced by: and interview, the facility over power strips were	K 924	checked on 5/9-10/17 for UI, unay Power Strips and none were found prosent. 3. Asystematic approach to ensur compliance with this standard will educate the Maintenance and Housekeeping Staff on what is an approved and unapproved UI. Pow and that only Medical Equipment is resident's from may be plugged in strip. Going forward, new Hubbell Receptable Adapter Plates with policy boxwiring and assembly installation be used in place of the power strip resident rooms with notification of these outlets are only to be used for instinctioned to ensure compliance with standard.	proved i to be e be to cr Strip n the to the 4 Plex table n will in the		
O df re no 2. co no 3.	rector on 5/9/17 bott vealed medical equi m-approved power s Resident room 50; wer strip that was no Resident room 50;	2 had bod pluggod Into of UL 1363A. 7 had bed and oxygen nto power strip that was		4. The Quality Assurance Staff will maintain an audit on a monthly bas ensure that only the Hubbell 4-Plex. Receptacle Adapter Plates with port boxwiring and assembly installation puresed in the resident's room for megulpment. The results of the audit be presented at the monthly Quality Assurance and Safety Committee meetings.	able will edical	·	

Paolity ID; TH9003

If continuetion sheet Page 4 of 5

ND PLAN	TOF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIET/CLIA IDENTIFICATION NUMBER:		TIPLE CONSTRUCTION		MB NO. 093 (X3) DATE SUR COMPLET	RVEY
NAME OF		445483	B. Wing		·ui -		
CORNE	PROVIDER OR SUPPLIER RSTONE VILLAGE			STREET ADDRESS, CIT 2012 SHERWOOD DR JOHNSON CITY, TN	IVE	05/09/2	017
(X4) ID PREFIX TAG		D'ÉMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL GC IDENTIFYING INFORMATION)	. ID PREFII TAG	PROVIDENT X (EACH CORRE CROSS-REFERE	3 PLAN OF CORRECTION COTIVE ACTION SHOULD NOED TO THE APPROPS DEFICIENCY)	utore lanes	(XX) APLE (I FLX(T)
- 1	The maintenance di deficiencies were ide	room 609 had an extension rector was present when the entified and was	Κg	-			
							-
	· ,						
1C DECTA	2-99) Previous Vorsione Obsi					}	